

JAN - 7 1996

DIV OF OIL, GAS & MINING

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/95 To (mo./yr.) 1/96
2. DOGM File Number (Mine No): M /035 /009
3. Mine Name: Barneys Canyon Mine
4. Mineral(s) Mined (or permitted to mine): Gold
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):  
SW 1/4, 1/4, Section 36, Township 25, Range 3W  
SW 1/4, 1/4, Section 2, Township 35, Range 3W  
SE 1/4, 1/4, Section 3, Township 35, Range 3W
7. Name of Operator or Company: Kennecott Corporation
8. Permanent Street Address : P.O. Box 311  
City, State, Zip: Bingham Canyon, UT 84006-0311  
Phone: (801) 569-7200
9. Company Representative (or designated operator):  
Name: Dennis M. Kerstiens  
Title: General Manager  
Business Address: P. O. Box 311  
City, State, Zip: Bingham Canyon, UT 84006-0311  
Phone: (801) 569-7200

☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 2,402,589 Tons

3. How much **additional acreage** was disturbed during the past year? 135 Acres
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Topsoil removal in permitted disturbance area.

To be used for future reclamation. Additional leach pads.

North Barneys pit area.

Melco North dump area.

5. How much acreage was **reclaimed** during the past year? 0

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Dozed approx. 80% of the Barneys Canyon 6300 dump to nominal 2 1/2:1 slope.

Topsoil applied to dump. Will seed as weather permits.

7. What is the **total disturbed acreage** at years end? 895

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Remove 300 K yards topsoil from Barneys Canyon. Complete dozing,  
topsoiling and seed 6300 dump. Grade Barneys 6500 dump and prepare  
for seed.

**NOTE:** Section III., "Additional Information" applies only to large mining operations.

### III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. Signature Requirement

**I hereby certify that the foregoing is true and correct.**


Name (Typed or Print):

Dennis M. Kerstiens

Title of Operator:

General Manager

Signature of Operator:




Date:

January 12, 1996



2 JK  
Kennecott Barneys Canyon Mining Company  
8200 South 9600 West  
P. O. Box 311  
Bingham Canyon, UT 84006-0311  
(801) 569-7200  
FAX (801) 569-7190

Dennis M. Kerstiens  
General Manager



**Kennecott**  
Minerals

January 12, 1996

D. Wayne Hedberg  
Permit Supervisor  
Department of Natural Resources  
Division of Oil, Gas and Mining  
335 West North Temple  
Salt Lake City, UT 84180-1203

Dear Mr. Hedberg:

Attached please find the annual report of mining operations as requested in your letter of December 13, 1995.

The report includes Mining operations for the Barneys Canyon Mine for 1995.

If you require further information, please call.

A handwritten signature in dark ink, appearing to read "D.M. Kerstiens".

Dennis M. Kerstiens  
General Manager  
Barneys Canyon Mine

DMK/ppb

Attachment